

Penn Reel Parts list for:

Penn Reel Parts list for: Mod				: 1050	
KEY	PART		KEY	PART	
NO	NO.	DESCRIPTION	NO	NO.	DESCRIPTION
1	1-105C	HOUSING W/ BUSHING EMBLEM	31A	31A-103	BAIL WIRE MOUNTING SCREW
2	2A-105	HOUSING BUSHING	32	32-105C	BAIL SPRING
2A	2A-105	COVER BUSHING	34	34-105	BAIL ARM
3	3-105C	DOG MOUNTING SCREW	34A	34A-105	BAIL ARM SPACER
4	4-105C	DOG W/ FINGER SPRING	35	35-105C	LINE ROLLER
6A	6A-105C	ECCENTRIC	36	36-105	BAIL STUD SCREW
6D	6D-105	ECCENTRIC SPRING	36A	36A-105	LOCK WASHER
6E	6E-105	ECCENTRIC LEVER	38	38-105	ROTOR NUT
6F	31-101	ECCENTRIC LEVER MOUNTING SCREW	V 39	39-105C	CROSSWIND SHAFT
8	8-105C	MAIN GEAR ASSEMBLY	43	43-105C	CROSSWIND ARM
8A	8A-105	MAIN GEAR SHIM	43A	43A-105C	CROSSWIND BLOCK
10	10-105C	ANTI-REVERSE RATCHET	43B	43B-105	CROSSWIND ARM SCREW
15	15-105	HANDLE (COMLETE)	45	45-105C	HOUSING COVER W/ BUSHING
15B	15B-105	HANDLE SHAFT	46	46-103	HOUSING COVER SCREW (3 REQ.)
15C	15C-105	HANDLE PIVOT PIN	46A	31-101	ROTOR END COVER SCREW
16	16-105	HANDLE COLLAR	47	47-105	SPOOL (COMPLETE)
19	19-105C	PINION GEAR	49	49-103	CLICK SPRING
19A	19A-105C	PINION GEAR SPACER	49A	28D-101	CLICK SPRING SCREW
20	20-105C	BALL BEARING	50	23-103	BAIL SPRING COVER SCREW
21	21-105C	BEARING COVER	51	51-105	RETAINING RING
23	23-105	BEARING COVER SCREW	52	52-105C	DRAG KNOB
24	24-105C	BAIL WIRE	56	56T-105	DRAG WASHER (TEFLON) (3 REQ.)
27	27-105C	ROTOR CUP	57	57-105	DRAG WASHER (KEYED) (2 REQ.)
27A	27A-105C	ROTOR END COVER	58	58-105	DRAG WASHER (EAR)
28	28-105C	TRIP LEVER	60	60-105	THRUST WASHER (TEFLON)
	28A-105C	CAM LEVER	106	106-105C	CAM LEVER SPRING
28B	28B-105	CAM LEVER MOUNTING SCREW	132	132-105C	ROLLER WASHER
	28C-105C	TRIP CAM	227	227-105C	BAIL SPRING COVER
28D	46A-103	CAM MOUNTING SCREW	230	230-105C	SILENT DOG SPRING
31	31A-103	BAIL ARM SCREW	233	233-105	HOUSING HANDLE CAP

Model: 105C

NOTE: Many of www.pennparts.com schematics include changes that were either made by Penn, or errors found and corrected by our parts dept. SBT Ver 010910

NOTE: Penn originally had 2-105 listed as the housing and cover bushings, but that part did not fit in the housing. 2A-105 is the correct part.